






Using winbond win2000 3mode fdc drvier should be processed as follow:
1. enter device manager











2. processing update driver: *be careful must select the right item(floppy disk drives)







3. choose Update Driver then Driver wizard will be show




4. press "next"




4. choose the "Display a list of the" and press "next"




6press "Have Disk"




7. press "Browse"




8. select where the winbond 3mode driver is




9. press "Open"



10. press "OK"



11. press " Yes"



12. press "Next"



13.press "Finish" and winbond 3mode driver is update successful